

VEHICLE INSPECTION REPORT

001791

HAMM HD8 VV

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Reg. date	01/03/2015	Fuel Type	Diesel	Body Style	ROLLER
Year	2015	Colour	WHITE/GREY	Gearbox	Hydrostatic
Mileage	65 Hours Incorrect	VIN	H1992665	Axle Combi	Tandem

COLLECT FROM PRESTON ROLL BAR, VIBRATING ROLLER, PLATE UNREADABLE, NO STAMPED VIN

Tyres

NSF

NSR

OSF

OSR

Spare

Photos



